

ILPS Series Cable Assembly Wiring Guide

5-Pin M-12 Connector		
I/O Function	Pin	Cable Color
+ Power Input	1	Brown
Common Ground	2	White
Voltage Output	3	Blue
Current Output	4	Black
SenSet Calibration	5	Gray

5-Pin Minifast Connector		
I/O Function	Pin	Cable Color
+ Power Input	1	Brown
Common Ground	2	White
Voltage Output	3	Blue
Current Output	4	Black
SenSet Calibration	5	Gray

6-Pin PT06 Connector		
I/O Function	Pin	Cable Color
Signal Output	A	Green
SenSet Calibration	B	White
Common Ground	D	Black
+ Power Input	E	Red